



PARTS LIST			
ITEM	QTY	PART NUMBER	DESCRIPTION
1	2	7100-1920	Horz Stab_Tip Spar
2	1	7100-1880	Horz Stab_Angle Spar
3	1	7100-1960	Spar_Inner Horz
4	2	7100-1940	Front Cradle_Horz Stab
5	1	7100-1820	HS Trailing Edge Spacer
6	1	7100-1930	Horizontal Stab_Surface_22 GA
7	1	7100-8740	HS Cover- Left
8	2	AN960-416	1/4" Flat Washer x .062"
9	2	AN4-20A	1/4"-28 x 2"
10	6	97482A273	187 Rivet x .375
11	6	8 - 32 x 3/16	Button Head Cap Screw

Outer skin not shown for clarity

Press solid rivets from opposite side for uniform look. (Right & Left hand parts)

PART NAME:

PART NUMBER:
Horz Stab_Sub Assy



31196 490th Street, Kasota, MN 56050
507-243-3991
sales@gyrotech.com www.gyrotech.com
THIS DRAWING AND THE INFORMATION HEREIN IS THE EXCLUSIVE PROPERTY OF GYRO TECHNIC INC AND IS NOT TO BE REPRODUCED OR USED TO MANUFACTURE ITEMS FOR USE OR SALE BY ANY OTHER PERSON OR CONCERN WITHOUT THE WRITTEN PERMISSION OF GYRO TECHNIC INC.